
# GROUP D




EXPLODED VIEW:
GTS LOAD CENTER
DRAWING #: 0H6388

REVISION: J-2542-B
DATE: 08/20/12

EXPLODED VIEW: GTS LOAD CENTER
DRAWING #: 0H6388

# GROUP D

APPLICABLE TO:

| ITEM | PART # | QTY. | DESCRIPTION | 10 | 12 | 14 | 16 | CIRCUIT |
|---|---|---|---|---|---|---|---|---|
| 1 | 0G80700ST14 | 1 | GTS LOAD CENTER ENCLOSURE GRAY | | | | | |
| 2 | 0G81020ST14 | 1 | COVER 10 POS.GTS LOAD CTR GRAY | | | | | |
| | 0G81030ST14 | 1 | COVER 12 POS.GTS LOAD CTR GRAY | | | | | |
| | 0G81040ST14 | 1 | COVER 14 POS.GTS LOAD CTR GRAY | | | | | |
| | 0G81060ST14 | 1 | COVER 16 POS.GTS LOAD CTR GRAY | | | | | |
| 3 | 0C2237 | 1 | TRANSFER SWITCH HOME STANDBY 100A 2P 250V | | | | | |
| 3A | 077220 | 1 | COIL UTILITY | | | | | |
| 3B | 077220A | 1 | COIL STANDBY | | | | | |
| 4 | 074908 | 4 | SCREW HHTT M5-0.8 X 10 | | | | | |
| 5 | 024912 | 1 | SCREW TAPTITE 1/4-20 X 5/8 | | | | | |
| 6 | 0A1658 | 1 | LOCK WASHER, SPECIAL-1/4" | | | | | |
| 7 | 063617 | 1 | RELAY PANEL 12VDC DPDT 10A@240VAC | | | | | |
| 8 | 0E7889 | 1 | 12CIR L/CENTR 125A/240V (ALSO USED FOR 10 CIRCUIT) | | | | | |
| | 0F9213 | 1 | 16CIR L/CENTR 125A/240V (ALSO USED FOR 14 CIRCUIT) | | | | | |
| 9 | 0A1495 | 4 | SCREW HHTT M4-0.7 X 10 | | | | | |
| 10 | 0J8111 | 2 | RIVET POP .156 X .25-.37 ALUM | | | | | |
| 11 | 081108 | 1 | PLUG PLASTIC | | | | | |
| 12 | 0G8095AST14 | 1 | HARNESS ADAPTER PLATE GRAY | | | | | |
| 13 | 0G81300ST14 | 1 | SUBPLATE GTS LOAD CENTER GRAY | | | | | |
| 14 | 0F4790 | 5.28" | U-CHANNEL | | | | | |
| 15 | 023897 | 6 | WASHER FLAT #10 ZINC | | | | | |
| 16 | 022717A | 1 | GROMMET 3/8 X 1/16 X 1/4 | | | | | |
| 17 | 0E6155 | 1 | ARM EXTENDER PIN | | | | | |
| 18 | 0G8233A | 4 | CABLE TIE SELF MOUNTING 4.3LG | | | | | |
| 19 | 0G8139 | 1 | HARN GTS-MAIN PNL 10CIR W/NEUT | | | | | |
| | 0G8140 | 1 | HARN GTS-MAIN PNL 12CIR W/NEUT | | | | | |
| | 0H6394 | 1 | HARN GTS-MAIN PNL 14CIR W/NEUT | | | | | |
| | 0G8141 | 1 | HARN GTS-MAIN PNL 16CIR W/NEUT | | | | | |
| 20 | 074138 | 3 | LUG QUICK DISCONNECT NI-S 10X45 DEG BRASS / TIN | | | | | |
| 21 | 036933 | 6 | SCREW PPHM #10-32X3/8 | | | | | |
| 22 | 077033 | 6 | LUG SLDLSS 1/0-#14X9/16 AL/CU | | | | | |
| 23 | 048766 | 1 | BLOCK TERM 20A 2 X 6 X 1100V | | | | | |
| 24 | 022152 | 6 | WASHER LOCK #10 | | | | | |
| 25 | 0A7215 | 10 | SCREW SW 1/4"-20 X 5/8" WITH WASHER | | | | | |
| 26 | 066849 | 2 | SCREW HHTT M5-0.8 X 16 (10, 12, 14, 16 CIRCUIT) | | | | | |
| 27 | 0H6399A | 1 | HARNESS LOAD CTR INT.CONN 10-16 (NOT SHOWN) | | | | | |
| | 0H6399B | 1 | HARNESS LOAD CTR INT.CONN T1 (NOT SHOWN) | | | | | |
| | 0H6399C | 1 | HARNESS LOAD CTR INT.CONN T2 (NOT SHOWN) | | | | | |
| 28 | 0D2572 | 1 | FUSEBLOCK 30A 600V 3POS W/SQ | | | | | |
| 29 | 073590A | 3 | FUSE 5A | | | | | |
| 30 | 0E7888 | A/R | CIRCUIT BREAKER 20A 2P | 1 | | 1 | 1 | |
| 31 | 0E7888A | A/R | CIRCUIT BREAKER 30A 2P | 1 | 1 | | | |
| 32 | 0E7888B | A/R | CIRCUIT BREAKER 15A 1P | 3 | 5 | 4 | 5 | |
| 33 | 0E7888C | A/R | CIRCUIT BREAKER 20A 1P | 3 | 3 | 6 | 5 | |
| 34 | 0E7888D | A/R | CIRCUIT BREAKER 40A 2P | | 1 | 1 | 1 | |
| 35 | 0E7888E | A/R | CIRCUIT BREAKER 50A 2P | | | | 1 | |
| 36 | 0G80860ST14 | 1 | HARNESS ENTRY COVER GRAY | | | | | |
| 37 | 0H6395 | 1 | HARN GTS-EXT CONN BOX 8KW | | | | | |
| | 0H6396 | 1 | HARN GTS-EXT CONN BOX 10KW | | | | | |
| | 0H6397 | 1 | HARN GTS-EXT CONN BOX 14/17KW | | | | | |
| | 0E7889 | 1 | 12CIR L/CENTR 125A/240V (ALSO USED FOR 10 CIRCUIT) | | | | | |