





WIRING - DIAGRAM

EW HOMESTANDBY

DRAWING #: 0E8115

GROUP G



LEGEND:

ALT - D. C. CHARGE ALTERNATOR
BAT - 12VDC BATTERY
C1 - CONNECTOR 1 (ENGINE)
CC - STARTER CONTACTOR
DEG - DRIVER ELEC. GOVERNOR
DIST- DISTRIBUTOR
FS - FUEL SOLENOID
GND1- GROUND (SENSING/LOW AMP)
GND2- GROUND (POWER/HIGH AMP)
GOV - ELEC. GOVERNOR ACTUATOR

LEGEND [CONT.]:

HCT	-	HIGH COOLANT TEMP SWITCH
IC	-	IGNITION COIL
IM	-	IGNITION MODULE
J-1	-	JUNCTION 1 (ON PCB)
J-2	-	JUNCTION 2 (ON PCB)
JB	-	JUNCTION BLOCK (RUN POWER)
LPS	-	LOW OIL PRESSURE SWITCH
MP1	-	MAGNETIC PICK-UP
R1	-	50 WATT RESISTOR
SM	-	STARTER MOTOR
WLS	-	COOLANT LEVEL SWITCH

WIRING - DIAGRAM

EW HOMESTANDBY

DRAWING #: 0E8115