

# **ERRATA SHEET**

**ALL 8.5 kW THROUGH 15 kW HOME STAND-BY GENERATORS WITH  
GT-990/760 ENGINES**

**2/24/06**

## **! IMPORTANT INFORMATION !**

THE SPARK PLUG GAP FOR ALL 8.5 kW THROUGH THE 15 kW HOME STAND-BY GENERATORS WITH THE GT-990/760 ENGINES SHOULD BE SET AT 1.02 mm (0.040 inch). THE RECOMMENDED SPARK PLUG IS CHAMPION #RC12YC (PART NO. 0G0767A).