



SEE ITEMS 32-37
FOR APPROPRIATE
PART NUMBERS
&
QUANTITIES

EXPLODED VIEW:
GTS LOAD CENTER
DRAWING #: 0G8786

EXPLODED VIEW: GTS LOAD CENTER

DRAWING #: 0G8786

GROUP D

APPLICABLE TO: 2008 HSB

| ITEM | PART # | QTY. | DESCRIPTION |
|------|-------------|-------|--|
| 1 | 0G80700ST14 | 1 | GTS LOAD CENTER ENCLOSURE GRAY |
| 2 | 0G81010ST14 | 1 | COVER 8 POS GTS LOAD CTR GRAY |
| | 0G81020ST14 | 1 | COVER 10 POS GTS LOAD CTR GRAY |
| | 0G81030ST14 | 1 | COVER 12 POS GTS LOAD CTR GRAY |
| | 0G81040ST14 | 1 | COVER 14 POS GTS LOAD CTR GRAY |
| | 0G81060ST14 | 1 | COVER 16 POS GTS LOAD CTR GRAY |
| 3 | 0C2237 | 1 | TRANSFER SWITCH HOME STANDBY 100A 2P 250V |
| 3A | 077220 | 1 | COIL UTILITY |
| 3B | 077220A | 1 | COIL STANDBY |
| 4 | 074908 | 4 | SCREW HHTT M5-0.8 X 10 |
| 5 | 024912 | 1 | SCREW TAPTITE 1/4-20 X 5/8 |
| 6 | 0A1658 | 1 | LOCK WASHER, SPECIAL-1/4" |
| 7 | 063617 | 1 | RELAY PANEL 12VDC DPDT 10A@240VAC |
| 8 | 0E7889A | 1 | 8 CIR LICNTR 125A/240V |
| | 0E7889 | 1 | 12 CIR LICNTR 125A/240V (ALSO USED FOR 10 CIRCUIT) |
| | 0F9213 | 1 | 16 CIR LICNTR 125A/240V (ALSO USED FOR 14 CIRCUIT) |
| 9 | 0A1495 | 4 | SCREW HHTT M4-0.7 X 10 |
| 10 | 0A1661 | 2 | RIVET POP .156" X .675" |
| 11 | - | - | - |
| 12 | 081108 | 1 | PLUG PLASTIC |
| 13 | 0G8095AST14 | 1 | HARNESS ADAPTER PLATE GRAY |
| 14 | 0G81300ST14 | 1 | SUBPLATE GTS LOAD CENTER GRAY |
| 15 | 0F4790 | 5.28" | U-CHANNEL |
| 16 | 023897 | 6 | WASHER FLAT #10 ZINC |
| 17 | 022717A | 1 | GROMMET 3/8 X 1/16 X 1/4 |
| 18 | 0E6155 | 1 | ARM EXTENDER PIN |
| 19 | 0G8233A | 4 | CABLE TIE SELF MOUNTING 4.3LG |
| 20 | 0G8138 | 1 | HARN GTS-MAIN PNL 8 CIR W/NEUT |
| | 0G8139 | 1 | HARN GTS-MAIN PNL 10 CIR W/NEUT |
| | 0G8140 | 1 | HARN GTS-MAIN PNL 12 CIR W/NEUT |
| | 0G7955 | 1 | HARN GTS-MAIN PNL 14 CIR W/NEUT |
| | 0G8141 | 1 | HARN GTS-MAIN PNL 16 CIR W/NEUT |
| 21 | 074138 | 3 | LUG QUICK DISCONNECT NI-S 10X45 DEG BRASS/ TIN |
| 22 | 036933 | 6 | SCREW PPHM #10-32X3/8 |
| 23 | 077033 | 6 | LUG SL DLSS 1/0-#14X9/16 ALICU |
| 24 | 0D4698 | 1 | BLOCK TERM 20A 6 X 3 X 1100V |
| 25 | 022152 | 6 | WASHER LOCK #10 |
| 26 | 0A7215 | 10 | SCREW SW 1/4"-20 X 5/8" WITH WASHER |
| - | - | - | - |
| 27 | 066849 | 2 | SCREW HHTT M5-0.8 X 16 (8, 10, 12, 14, 16 CIRCUIT) |
| 28 | 0G7954A | 1 | HARNESS LOAD CTR INT.CONN 8-16 (NOT SHOWN) |
| | 0G7954B | 1 | HARNESS LOAD CTR INT.CONN T1 (NOT SHOWN) |
| | 0G7954C | 1 | HARNESS LOAD CTR INT.CONN T2 (NOT SHOWN) |
| 29 | 0D2572 | 1 | FUSEBLOCK 30A 600V 3POS W/SQ |
| 30 | 073590A | 3 | FUSE 5A |
| 31 | 0G8487 | 1 | BATTERY CHARGER ASSY |
| | | | 8 10 12 14 16 CIRCUIT |
| 32 | 0E7888 | A/R | CIRCUIT BREAKER 20A 2P 1 1 1 |
| 33 | 0E7888A | A/R | CIRCUIT BREAKER 30A 2P 1 1 1 |
| 34 | 0E7888B | A/R | CIRCUIT BREAKER 15A 1P 5 3 5 4 5 |
| 35 | 0E7888C | A/R | CIRCUIT BREAKER 20A 1P 1 3 3 4 5 |
| 36 | 0E7888D | A/R | CIRCUIT BREAKER 40A 2P 1 1 1 |
| 37 | 0E7888E | A/R | CIRCUIT BREAKER 50A 2P 1 1 |
| 38 | 0G80860ST14 | 1 | HARNESS ENTRY COVER GRAY |
| 39 | 0G7951 | 1 | HARN GTS-EXT CONN BOX 8KW |
| | 0G7952 | 1 | HARN GTS-EXT CONN BOX 10KW |
| | 0G7953 | 1 | HARN GTS-EXT CONN BOX 14/17KW |