

D

C

B


A

D

C

B

A



| SH     | I/I     | REV         | B                                       | WINDCHILL VERSION | B.3 |  |
|--------|---------|-------------|-----------------------------------------|-------------------|-----|--|
| ITEM # | PART #  | QTY         | DESCRIPTION                             |                   |     |  |
| 1      | OC2237  | 1           | XFRSW HSB 100A 2P 250V                  |                   |     |  |
| 2      | 074908  | 6           | SCREW HHTT M5-0.8 X 10 BP               |                   |     |  |
| 3      | 077033  | 6           | LUG SLDLSS 1/0-#14X9/16 AL/CU           |                   |     |  |
| 4      | OG7624  | 6           | SCREW PPHM #10-32 X 5/16                |                   |     |  |
| 5      | 022152  | 6           | WASHER LOCK #10                         |                   |     |  |
| 6      | 074138  | 1           | LUG DIS OK N1-S 10X45 DEG BR/T          |                   |     |  |
| 7      | OE7886H | 1           | CB 0100A 2P 240V S B02 LB               |                   |     |  |
| 8      | OE7890  | 1           | BRKT CB MTG BACK                        |                   |     |  |
| 9      | OG5780A | 1           | ASSY WIRE 2AWG 5.375" #N1A BLK          |                   |     |  |
| 10     | OG5780B | 1           | ASSY WIRE 2AWG 6.875" #N2A BLK          |                   |     |  |
| 11     | 0A1495  | 6           | SCREW HHTT M4-0.7 X 10 BP               |                   |     |  |
| 12     | 0J4908  | 1           | DECAL CUSTOMER CONN RTS                 |                   |     |  |
| **     | 13      | OK0103      | RELAY PNL 12VDC DPDT 10A@240VA          |                   |     |  |
| **     | 14      | OD2572      | FUSEBLOCK 30A 600V 3POS W/SQ            |                   |     |  |
| **     | 15      | 073590A     | FUSE 5A X BUSS                          |                   |     |  |
| **     | 16      | OD7393T     | TERM BLOCK 3P UL 12-20AWG               |                   |     |  |
| **     | 17      | OF2659      | SCREW HHTT M3-0.5 X 6 BP                |                   |     |  |
| **     | 18      | OK0124      | SCREW PHTT M3-0.5 X 25                  |                   |     |  |
| **     | 19      | OK0108      | ASSY-NEUT BLK 100A                      |                   |     |  |
| **     | 20      | 090388      | SCREW HHTT M6-1.0 X 12 ZINC             |                   |     |  |
| **     | 21      | 026902      | SCREW HHTT #8-32 X 1/4 CZ               |                   |     |  |
| **     | 22      | OK01120ALOR | ENCLOSURE 100/200A XFER SW_RAW          |                   |     |  |
| **     | 23      | OK01130ALOR | COVER 100A XFER SWITCH_INST_RAW         |                   |     |  |
| **     | 24      | OK0114      | SUBPLATE, 100/200A XFER SW              |                   |     |  |
| **     | 25      | OK11120ALOR | COVER INSIDE 100A SE GRAY_RAW           |                   |     |  |
| **     | 26      | OK1119      | RISER 100A SERV ENT                     |                   |     |  |
| *      | 27      | OK1098      | DECAL RTS TRANSFER SW GENERAC           |                   |     |  |
| *      | 28      | OK1736A     | DECAL, XFER SW SE 100A 120/240          |                   |     |  |
| *      | 29      | OE3484      | DECAL WARN MANUAL OPER HANDLE           |                   |     |  |
| *      | 30      | OF9969      | DECAL UTILITY DISCONNECT                |                   |     |  |
| *      | 31      | OK1018      | DECAL, NEUTRAL CONNECTION               |                   |     |  |
| *      | 32      | OK1167      | WIRE NEUTRAL TO GROUND CONNECTION       |                   |     |  |
| *      | 33      | OK1738      | DECAL TEST SEQUENCE 100-200A SE         |                   |     |  |
| *      | 34      | OD3587      | DECAL, FUSE REPLACEMENT                 |                   |     |  |
| *      | 35      | OG3259      | DECAL TERMINAL SHOCK HZD BI             |                   |     |  |
| *      | 36      | OG3274      | DECAL LIVE CIRCUIT ENG/FRN/SPN          |                   |     |  |
| *      | 37      | OH6389      | DECAL UTILITY LOAD SENSE 240V           |                   |     |  |
| *      | 38      | OK9467      | LIMIT SWITCH SPST 16A                   |                   |     |  |
| *      | 39      | OE7213      | SCREW THUMB 1/4-20 X1/2 W/SHLD          |                   |     |  |
| *      | 40      | 0J8202      | LUG SLDLSS 2/0-#14X#10-32X.125          |                   |     |  |
| *      | 41      | 026850      | WASHER LOCK EXT 1/4 STL                 |                   |     |  |
| *      | 42      | OG8411      | NUT HEX FL WHIZ 1/4-20                  |                   |     |  |
| *      | 43      | 085889      | NUT HEX 1/4-20 SS                       |                   |     |  |
| *      | 44      | 022473      | WASHER FLAT 1/4-M6 ZINC                 |                   |     |  |
| ***    | 45      | OE6193      | BRACKET, ARM EXTENDER                   |                   |     |  |
| ***    | 46      | OD6162      | RIVET POP .156 X .362 AL                |                   |     |  |
| ***    | 47      | OE6155      | PIN ARM EXTENDER                        |                   |     |  |
| ***    | 48      | OK9468      | SCREW PPH M3X15 SEMS                    |                   |     |  |
| ***    | 49      | OK9496      | WIRING HARNESS 100/200A RTS (NOT SHOWN) |                   |     |  |
| ***    | 50      | 058000E     | NUT TRIC 1/4-20 X .525                  |                   |     |  |

DRAWING CREATED FROM PRO/ENGINEER 3D FILE. ECO MODIFICATION TO BE APPLIED TO SOLID MODEL ONLY.

GENERAL ASSEMBLY DRAWING