

D

C

B

A

D

C

B


A

| ITEM # | PART #      | QTY | DESCRIPTION                            |
|--------|-------------|-----|----------------------------------------|
| 1      | 0D9618      | 1   | XFRSW HSB 200A 2P 250V                 |
| 2      | 074908      | 5   | SCREW HHTT M5-0.8 X 10 BP              |
| 3      | 0E7283      | 1   | CB 0150A 2P 240V S QN2 LL              |
| 4      | 0E3664      | 1   | BASE, ON CIRCUIT BREAKER               |
| 5      | 036918      | 2   | SCREW PPHM #8-32 X 1/2                 |
| 6      | 0G9299      | 2   | WIRE 3/0 NI,N2                         |
| 7      | 0E3375      | 6   | LUG SLDLSS 250-#6 AL/CU                |
| 8      | 0F1252      | 6   | SCREW BHSC 1/4-20 X 3/8                |
| 9      | 022097      | 6   | WASHER LOCK M6-1/4                     |
| 10     | 0E6033      | 4   | 90 DEGREE DN SPADE CONNECTOR           |
| 11     | 0E6034      | 1   | STRAIGHT SPADE CONNECTOR               |
| 12     | 0J8202      | 1   | LUG SLDLSS 2/0-#14X#10-32X.125         |
| 13     | 026850      | 2   | WASHER LOCK EXT 1/4 STL                |
| 14     | 0G8411      | 6   | NUT HEX FL WHIZ 1/4-20                 |
| 15     | 0K1914      | 1   | WIRE NEUTRAL CONNECTION SIE            |
| 16     | 0K0108A     | 1   | ASSY-NEUT BLK 200A W/TAP               |
| 17     | 090388      | 2   | SCREW HHTT M6-1.0 X 12 ZINC            |
| 18     | 0K01170ALOR | 1   | ENCLOSURE 200A SE XFRSW RAW            |
| 19     | 0K01180ALOR | 1   | COVER,200A SE XFRSW RAW                |
| 20     | 0K0119      | 1   | SUBPLATE,200A SE XFER SW               |
| 21     | 0G93000ALOR | 1   | CB RISER BRACKET 200A GENERAC RAW      |
| 22     | 0G97730ALOR | 1   | COVER INSIDE 200A SE SIE RAW           |
| 23     | 022473      | 4   | WASHER FLAT 1/4-M6 ZINC                |
| 24     | 085889      | 1   | NUT HEX 1/4-20 SS                      |
| 25     | 0D2572      | 1   | FUSEBLOCK 30A 600V 3POS W/SQ           |
| 26     | 073590A     | 3   | FUSE 5A X BUSS                         |
| 27     | 0A1495      | 5   | SCREW HHTT M4-0.7 X 10 BP              |
| 28     | 0K0103      | 1   | RELAY PNL 12VDC DPDT 10A@240VA         |
| 29     | 0F2659      | 2   | SCREW HHTT M3-0.5 X 6 BP               |
| 30     | 0D7393T     | 1   | TERM BLOCK 3P UL 12-20AWG              |
| 31     | 0K0124      | 2   | SCREW PHTT M3-0.5 X 25                 |
| 32     | 0D3587      | 1   | DECAL, FUSE REPLACEMENT                |
| 33     | 0E3484      | 1   | DECAL WARN MANUAL OPER HANDLE          |
| 34     | 0G3259      | 1   | DECAL TERMINAL SHOCK HZD B1            |
| 35     | 0G3274      | 1   | DECAL LIVE CIRCUIT ENG/FRN/SPN         |
| 36     | 026902      | 1   | SCREW HHTT #8-32 X 1/4 CZ              |
| 37     | 0H1765A     | 1   | DECAL UTILITY SOURCE CONNECTION        |
| 38     | 0H1765B     | 1   | DECAL GENERATOR/CUSTOMER CONN          |
| 39     | 0H1765C     | 1   | DECAL UTILITY DISCONNECT               |
| 40     | 0H6389      | 1   | DECAL UTILITY LOAD SENSE 240V          |
| 41     | 0D6162      | 2   | RIVET POP .156 X .362 AL               |
| 42     | 0E6155      | 1   | PIN ARM EXTENDER                       |
| 43     | 0E6193      | 1   | BRACKET, ARM EXTENDER                  |
| 44     | 0E7213      | 1   | SCREW THUMB 1/4-20 X1/2 W/SHLD         |
| 45     | 0J4908      | 1   | DECAL CUSTOMER CONN RTS                |
| 46     | 0K1018      | 1   | DECAL, NEUTRAL CONNECTION              |
| 47     | 0K1272      | 1   | DECAL TRANSFER SW SIEMENS              |
| 48     | 0K1736B     | 1   | DECAL,XFER SW SE 150A 120/240          |
| 49     | 0K1738      | 1   | DECAL TEST SEQUENCE 100-200A SE        |
| 50     | 0K9467      | 1   | LIMIT SWITCH SPST 16A                  |
| 51     | 0K9468      | 2   | SCREW PPH M3X15 SEMS                   |
| 52     | 064761      | 4   | TIE WRAP UL 5.6 X .10 NATL (NOT SHOWN) |
| 53     | 0K9497      | 1   | HARN 200A XFER SW SE (NOT SHOWN)       |

-SUPPLIED WITH HARNESS ITEM #53

| PART NUMBER | DESCRIPTION                     |
|-------------|---------------------------------|
| OK9485      | ASSEMBLY 200A SERVICE ENTR SIEM |
| OK9485A     | EXPLODED VIEW DRAWING           |

| GENERAL TOLERANCES UNLESS NOTED            |          |
|--------------------------------------------|----------|
| ALL XX                                     | ± .04 MM |
| XXX                                        | ± .04 MM |
| XXXX                                       | ± .05 MM |
| ALL ANG                                    | ± .5°    |
| INTERPRET DIM AND TOL PER ASME Y14.5M-1994 |          |



**GENERAC**

TITLE  
ASSEMBLY 150A SERVICE  
ENTRANCE SIEMENS CB

|             |      |         |          |              |
|-------------|------|---------|----------|--------------|
| ISSUE DATE: | SIZE | CAGE NO | DWG NO   | REV          |
|             | D    | N/A     | OK9485\$ | B            |
| SCALE 0.300 |      | WT-KG   | 548.567  | SHEET 1 of 1 |

GENERAL ASSEMBLY DRAWING

DRAWING CREATED FROM PRO/ENGINEER  
3D FILE. ECO MODIFICATION TO BE  
APPLIED TO SOLID MODEL ONLY.

REFERENCE DRAWINGS  
OK9492 SCHEMATIC/WIRING DIAGRAMS  
OK1846 CARTON 30"5 X 14"2 X 7"8  
OK17275 TEST PROC HSB XFRSW  
OK0121 KIT, ENCL 200A SE AL SIEMENS

SECTION A-A

ITEM #23 MOUNTED UNDER  
SUBPLATE ITEM #20  
4 PLACES

SECTION B-B  
SCALE 0.800

TORQUE ITEM #8  
TO 72 IN-LBS

SECTION C-C  
SCALE 0.800

SECTION D-D  
SCALE 0.800