




ITEM #	PART #	QTY	DESCRIPTION
1	OL2911	1	XFRSW HSB 200A 2P 250V
2	G074908	5	SCREW HHTT M5-0.8 X 10 BP
3	OK0133	1	CB 200A 2POLE 240V 225AF
4	OK0973	2	SCREW RHM #8-32 X 2-1/2
5	0H6306	2	LUG SLDLSS 350 MCM-6 AL/CU
6	OG4413	2	SPACER 200 AMP TRANSFER SWITCH
7	024334	2	BOLT CARR 1/4-20 X 1
8	OK0130	2	BUSBAR 200A TRANSFER SW N1,N2
9	049897	4	SCREW SHC LOW M8-1.25 X 20 G8
10	G022129	4	WASHER LOCK SPRING 5/16 ZC
11	0E3375	4	LUG SLDLSS 250-#6 AL/CU
12	0F1252	4	SCREW BHSC 1/4-20 X 3/8
13	0E6033	4	90 DEGREE DN SPADE CONNECTOR
14	0E6034	1	STRAIGHT SPADE CONNECTOR
15	0J8202	1	LUG SLDLSS 2/0-#14 AL9CU
16	OK1081	1	WIRE NEUTRAL/GND CONNECTION
17	OK0108A	1	ASSY-NEUT BLK 200A W/TAP
18	G090388	2	SCREW HHTT M6-1.0 X 12 ZINC
19	10000000817	1	AL0R ENCLOSURE 200A SE XFRSW
20	10000000825	1	SUBPLATE,200A SE XFER SW
21	10000000819	1	COVER INSIDE 200A SE XFER SW
22	10000000830	1	AL0R COVER,200A SE XFRSW
23	0L1950A	1	DATA DECAL TSWS SE
24	0E3484	1	DECAL WARN MANUAL OPER HANDLE
25	OG9651A	1	DECALS, SERVICE ENTRANCE
26	OG9651B	1	DECALS, SERVICE ENTRANCE
27	OG9651C	1	DECALS, SERVICE ENTRANCE
28	OK1018	1	DECAL, NEUTRAL CONNECTION
29	026902	1	SCREW HHTT #8-32 X 1/4 CZ
30	OK1738	1	DECAL TEST SEQUENCE 100-200A SE
31	OG3274	1	DECAL LIVE CIRCUIT ENG/FRN/SPN
32	OG3259	1	DECAL TERMINAL SHOCK HZD BI
33	OK1098	1	DECAL RTS TRANSFER SW GENERAC
34	026850	2	WASHER LOCK EXT 1/4 STL
35	0L6700	1	SCREW THUMB 1/4-20 X 1/2 KNURL
36	085889	1	NUT HEX 1/4-20 SS
37	OG8411	8	NUT HEX FLANGE WHIZ 1/4-20
38	G022097	4	WASHER LOCK SPRING 1/4 ZC
39	OK8254	1	U-CLIP ADHESIVE
40	0E6155	1	PIN ARM EXTENDER
41	0H7274	1	DECAL NEC COMPLIANCE
42	OK8414	1	CB TERMINAL COVER 2 POLE 240V
43	OK8628	2	SCREW PFHM 4-24 X 5/16 TCS
44	10000004183	1	ASSY SMART AC MODULE
45	10000005872	1	HARNESS 100/200A TS
46	10000008602	1	DECAL WCR NEC COMPLIANCE
47	10000037322	1	DECAL PROP 65 EN/SP/FR
48	G054634	1	BAG POLY 10 X 13 2MIL ZIP LOCK

*-FRONT DECAL PER MODEL

SUGGESTED LOCATION OF DECAL TO BE INCLUDED IN MANUAL BAG

PART NUMBER	DESCRIPTION	ITEM #33	MODEL #	MANUAL	WARRANTY
10000005789	ASSEMBLY 200A SERVICE ENTR GEN	OK1098	RXSW200A3	10000009569	OK9470
10000005798	ASSEMBLY 200A SERVICE ENTR HNYWL	OK1274	RXSM200A3	10000009532	OK3103
10000011659	ASSEMBLY 200A SERVICE ENTR GEN	OK1098	BUNDLED	10000009569	OK9470
10000011751	ASSEMBLY 200A SERVICE ENTR HNYWL	OK1274	BUNDLED	10000009532	OK3103
10000023153	ASSEMBLY 200A SERVICE ENTR DR	10000023086	G0041478	10000023119	10000023720
10000023501	ASSEMBLY 200A SERVICE ENTR POWERMATE	10000023483	BUNDLED	10000024160	10000028401

REFERENCE DRAWINGS
10000006038 SCHEMATIC/WIRING DIAGRAMS
OK1846 CARTON 30"5 X 14"2 X 7

GENERAL TOLERANCES UNLESS NOTED	
ALL XX = ± 0.4 MM	THIRD ANGLE PROJECTION
XX.X = ± 0.4 MM	
XX.XX = ± 0.15 MM	
ALL ANG = ± 1°	
INTERPRET DIM AND TOL PER ASME Y14.5M-1994	



TITLE
ASSEMBLY 200A SERVICE ENTRANCE GENERAC CB

ISSUE DATE:	SIZE	CAGE NO	DWG NO	REV
	D	N/A	10000005776	F
	SCALE	0.300	WT-KG 285116280.665 SHEET	1 of 1

GENERAL ASSEMBLY DRAWING