

This diagram illustrates the assembly of a 3D printer frame. The frame is shown in a perspective view, with dashed lines indicating the internal structure and the positions of various components. The components are labeled with numbers 1 through 6, corresponding to the parts list on the right.

- 1**: Screws used for mounting the frame and securing the components.
- 2**: Screws used for mounting the frame and securing the components.
- 3**: A circular component, likely a motor or a sensor, mounted on the frame.
- 4**: A long, flexible cable or hose, likely for the extruder or the bed.
- 5**: A short, rigid pipe or tube, likely for the extruder or the bed.
- 6**: A small, cylindrical component, likely a nozzle or a sensor.

The diagram shows the frame with various components already installed, including the extruder, the bed, and the motor. The components are labeled with numbers 1 through 6, corresponding to the parts list on the right.



EXPLODED VIEW: EV KIT FUEL HOSES AND FITTINGS D2.2L**DRAWING #: A0001454399****GROUP C****APPLICABLE TO:**

ITEM	PART#	QTY.	DESCRIPTION
1	048031N	6	CLAMP HOSE BAND .53
2	G067982	2	BARBED STR 3/8NPT X 5/16
3	10000020481	1	PRIMER
4	0C8008	2	HOSE 5/16 SAE 30R7 (38.7" LG)
5	0C8008	1	HOSE 5/16 SAE 30R7 (14.4"LG)
6	G025066	1	COUPLING FULL 3/8-18