

SERVICE ITEM ACCESSIBILITY CHART			
SERVICE ITEM	3. OL	50K1	3.9L 7
OIL FILL CAP	LOCATED ON LEFT VALVE COV		
OIL DIP STICK	THRU LEFT DOOR	THRU RIGHT DOOR	THRU LEFT DOOR
OIL FILTER	THRU LEFT DOOR	THRU RIGHT DOOR	THRU LEFT DOOR
OIL DRAIN HOSE	THRU LEFT DOOR	THRU LEFT DOOR	THRU LEFT DOOR
RADIATOR DRAIN HOSE	THRU RIGHT DOOR	THRU RIGHT DOOR	THRU LEFT DOOR
AIR CLEANER ELEMENT	NEITHER DOOR	NEITHER DOOR	NEITHER DOOR
SPARK PLUGS	BOTH DOORS	BOTH DOORS	BOTH DOORS
MUFFLERS	SEE NOTE 6	SEE NOTE 6	SEE NOTE 6
FAN BELT	SEE NOTE 6	SEE NOTE 6	SEE NOTE 6
BATTERY	THRU RIGHT DOOR	THRU RIGHT DOOR	THRU RIGHT DOOR

